

State of Utah

DIVISION OF WATER QUALITY



M/019/005

Michael O. Leavitt Dianne R. Nielson, Ph.D. Executive Director Don A. Ostler, P.E.


288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 Voice (801) 538-6016 Fax

(801) 536-4414 T.D.D.

February 16, 1995

DEPARTMENT OF ENVIRONMENTAL QUALITY

E. K. York Moab Salt, Inc. P. O. Box 1208 Moab, Utah 84532



Mechanical Integrity Tests on Injection Re: Wells Nos. 5, 6 and 15; Moab Salt Letters to the Utah Division of Water Ouality Dated December 6 and December 19, 1994; UIC

Permit No. UTU300001.

Dear Mr. York:

Thank you for the submittals noted above summarizing the results of the following injection well radioactive tracer mechanical integrity tests (MIT's):

- 1. October 10-12, 1994 -- Wells Nos. 5, 6 and 15 (No. 5 failed)
- November 9, 1994 -- Well No. 5 (Repeat MIT)

After field discussions with the logger, review of the final radioactive tracer test well logs and the repeat MIT report on Well No. 5, it is our opinion that injection wells Nos. 5, 6 and 15 have no significant leaks in their casings and no significant fluid movement into an USDW through vertical channels adjacent to their well bores. The October MIT's are hereby approved as proof of mechanical integrity for Well Nos. 6 and 15, and the November MIT is approved as proof of mechanical integrity for Well No. 5.

Sincerely,

Utah Water Quality Board

Don A. Ostler, P.E. **Executive Secretary**

DAO:JJ:ja

cc:

Dan Jackson, EPA Region VIII Dave Ariotti, District Engineer

Jim Adamson, S.E. Utah District Health Dept.

Utah Division of Oil, Gas and Mining

F:MS'94.MIT

FILE: MOAB SALT, INC. /UIC

